

On Sevilla street, at Julio Berdegúe Aznar Loop, on medians and private areas, such as in Puerto España, trees were trimmed to prepare for the storm season.



(669) 916 6106

(669) 913 44 53



WWW.UCCID.COM

 COLONOSSEL CID



Likewise, prior to the rainy season, as well as throughout the summer season, we have done the desilting, cleaning of rainwater drainage and drains at Burgos section, thus, we can manage to take out the rainwater in more efficient and speedier fashion.



The drains and the Marina, continued to be cleaned, with the support of the bio fence which prevent garbage from dumping into the sea, and to our navigation canals, given that a lot of trash continues to come in, as people carelessly throw trash into the creeks that go around many residential areas; the rain drags this trash contaminating our creeks. Regrettably, these creeks flow into the ocean and should not be carrying so much trash. The bio fences are cleaned daily, collecting 40 tons of trash per year, approximately.



There were improvements done to Doña Sol Street. The works to improve the drains, potable water piping, and cobble stone at the end of the street were completed. The works to replace the missing concrete pavers at a section of the street, are being planned.



(669) 916 6106



(669) 913 44 53



WWW.UCCID.COM



COLONOSLCCID



At the children´s park at La Isla section, the painting to the perimeter wall was done, and the concrete floor was repaired; also, artificial grass was installed at a section to serve as a soccer court (5.0 X 7.0m).



STORM MESH

Works done on the storm mesh, the holding metal posts and upper anchoring were replaced, and later, the mesh was also replaced at the Marina area sidewalk.



Works begun to replace the wastewater discharge piping on the main median at Julio Berdegué Aznar Loop.



(669) 916 6106

(669) 913 44 53

3

WWW.UCCID.COM



COLONOSCLCID



CAMERAS AND MONITORING CENTER PROJECT

The first phase was completed, in which new support equipment for cameras and microphones in the guard houses was installed.

Likewise, cameras at Julio Berdegué Aznar Loop and Reino de León were installed. At the El Toreo gate, they will be installed on the exterior in order to monitor the dividing wall.



THE EVALUATION OF THE SURVEILLANCE TEAM

The evaluation of the surveillance team performance is carried out daily.

Various meetings with the surveillance teams were carried out on the 18th of July (at 6 am, 2 pm, and 7 pm) according to the different work shifts.



A compact tractor to mow the lawn in green areas was purchased.





(669) 916 6106





(669) 913 44 53



We continue to work in a significant manner on the subject of speeding in our subdivision; during the month of November, we will continue with the campaign “Why the hurry”, when we will be handing out flyers to create awareness on the importance of abiding by the speed limits and in general to observe the road signage. Recently, the reflecting mini speed bumps were installed at the entrance of the subdivision, by the Club House, to encourage drivers to observe the proper speed during their route.



The works to modernize the water treating plant, begun; with this high-cost investment, aside from continuing to be at the cutting edge of environmental matters, the process and quality of the water shall improve, among other advantages, which will make it more efficient in all senses.



(669) 916 6106



(669) 913 44 53

5

WWW.UCCID.COM



COLONOSCLCID

